1100 / 1300 CLEARANCE SALE Updated 11/14/21

All of the parts on this list are unique to 1100/1300 (ADO16) cars, including MG1100 and Austin America. All are out of production; when our stocks are gone, there will be no more. Prices have never been lower. Order early for best selection. All sales final. Postage added at cost.

New lighting switch (toggle), 1100, 31837 \$24.95

New bolt, twin carb air cleaner assembly to carbs (2 required). ZCS 520 \$.40 each

New indicator switch, 1100 1st type (no light on stalk). 34432 \$49.00

New spring, inside oil filter, automatic transmission. 37H 2634 \$.25

New heater switch (toggle), 1100. 34514 \$19.00

New locktab, automatic torque converter. 27H 8804 \$.95

New indicator switch, 1100 3rd type (light on stalk, headlight flash). 35738 \$79.00

New rubber o-ring, inside 1300 metal air cleaner housing. 27H 6954 \$1.50

New wiper switch (rocker, 2-speed). 35889 \$9.95

New lighting switch (rocker, 4-prong, includes nacelle). 39298 \$14.95

New wedge/screw, rear brake adjuster. 27H 2203 \$2.00

New wiper switch (narrow rocker, 2-speed). 39748 \$9.95

New brake connection (1100, brass, 4-way, firewall mounted). 17H 7108 \$27.00

New taillamp assembly, MG1100, all red lenses. 53968 \$80.00

New rubber seal, automatic trans. oil filter assembly. 17H 2443 \$.25

New reverse lamp, model L696, Austin America, complete. 54519 \$29.00

New lens, clear plastic for Austin America reverse lamp. 54572287 \$5.00

New lens, light blue tinted plastic, America reverse lamp. 54578348 \$3.00

New mounting (rubber), exhaust. GEX 7097 \$2.00

New bracket, platform, rear exhaust mounting. GEX 7100 \$2.00

New bracket, exhaust mounting to differential, automatic. GEX 7109 \$2.00

New cover (chrome) for 54519 reverse lamp. 54578535 \$15.00

New wheel nut, standard all models. 88G 276 \$1.00

New gasket, lens seating, Austin America taillamp. 54580139 \$2.00

New channel, felt & rubber, door glass front (33" long). 34G 3450 \$3.00

New lens, clear glass, with gasket, America reverse lamp. 54582532 \$10.00

New window winder handle, MG 1100. 34G 2528 \$7.95

New taillamp, Austin America, with gasket. 54943 \$60.00

New wiper wheelbox kit, 2 pieces black plastic. 54704782 \$3.00

New bracket, exhaust to gearbox, single carb models. ACA 9846 \$4.00

New fuel filler hose, Countryman/Traveller models. 31G 1154 \$4.95

New bumper bolt, chrome, with nut & washer. ADA 5653 \$4.50

New bracket, part of automatic transmission bracing to firewall. 31G 1037 \$5.00

New outside door handles, early style with integral pushbutton and lock, supplied with two

keys. R/H ADA 5088, L/H ADA 5089, \$24.00 each

New throttle cable, early single-carb models (outer 18"). 31G 668 \$2.95

New adaptor, carb float chamber, aluminum, HS4 on 1300, America. AUD 2071 \$2.50

New clutch hose, all models. BCA 4736 \$14.95

New fork, throttle cable end connection, 31G 273 \$.95

New wheel stud, all models, front and rear. BTA 369 \$2.95

New engine steady arm, automatic transmission models. 31G 391 \$10.00

New bracket, exhaust pipe to gearbox, twin-carb models. 22G 396 \$2.00

New restrictor, nylon tube, HS4 carburetor. 12G 3436 \$.50

New **nut**, for ACA9837 mount at rear of remote shifter. **CNZ 106 \$.10**

New button clip, 2-door push & lock door handles. CZA 2559 \$1.50

New seal, oil filter canister to head, automatic models. 12G 1824 \$.70

New bonnet prop, rod type, over 20" long, CZA 8412 \$4.95

New bracket, lower radiator support. 12G 140 \$5.00

New front plate, engine mounting. 12G 1311 \$30.00

New chrome surround for front badge, Austin 1100 Mk1. 34G 553 \$5.00

New chrome surround for rear badge, Austin and Morris models. CZA 2213 \$5.00

New forward shaft/gear assembly, automatic transmission 22G 807 \$40.00

New primary gear for 1100 automatic (28 teeth). 22A 1064 \$35.00

New fastener assembly, 3-pc. turnbuckle for molded ignition shield. 13H 6461 \$2.50

New rear brake adjuster repair kit, replaces whole assembly. 2218 \$12.00

New door lock assembly, Right-Hand. ADA 5679 \$10.00

New compression union (brass) for steel hydrolastic line repair. 2254 \$4.00

New rubber plug for hole between torque converter cover and housing. 22A 1492 \$2.00

New camshaft, star drive version for early 1275cc. AEG 522 \$125.00

New quarter-lite assembly (rear side window), R/H, complete.. ARA 127 \$60.00

New inner tube, Vredestein 560/600/155-12 \$15.00

New temperature gauge, MG1100, Smiths BT 8101/01, 7H 9328 \$6.00

New spring, brake pedal return, automatics, 31G 398 \$2.00

New catch, rear side window, L/H, Austin America, ARA 1845 \$10.00

New temperature gauge, Austin America, Smiths BT 8116/00, 13H 4636 \$7.00

New glass lens for ribbon speedometer unit, with printing, Lens1 \$12.00

NOTE: For best service during this sale, we strongly recommend corresponding and placing orders by email to minicityus@aol.com. Telephone messages are not monitored every day.